

Sellersville FD Job 37265

The following pictures show the body continuing the weld and fit up process. The report also shows the pump house continues through the weld process and paint. Finally the pictures show the cab in paint.

































